CARR - 405

LOG HOUSE

Fenby Farm Road Westminster vicinity private

This is an unusual log house because of the lack of historical documentation about the structure. The house is built in the tradition of a mid-nineteenth century log farmhouse, especially with its siting along a bank with a full-story stone foundation on the main facade. However, the property is not shown on either of the mid-19th century maps of Carroll County. The house has recently been rehabilitated with exposed logs, an asphalt shingle roof, and a modern one-story rear addition.



COUNTY:

ADDRESS:

TOWN: LOCATION:


DEPARTMENT OF PLANNING AND DEVELOPME

WESTMINSTER PLANNING DISTRICT

	SUFVEY NUMBER: CARR-405
DEPARTMENT OF PLANNING AND DEVELOPMENT	NEGATIVE FILE NUMBER:
225. N. Center Street Westminster, Maryland 21157	UTM REFERENCES: Zone/Easting/Northing
WESTMINSTER PLANNING DISTRICT	
FIELD SHEETHISTORIC RESOURCES SURVEY	U.S.G.S. QUAD. MAP: New Windsor
	PRESENT FORMAL NAME:
COUNTY: CARROLL	ORIGINAL FORMAL NAME:
COWN: Westminter sicinity	
LOCATION: Fenby Farm Road	PRESENT USE: residure
rendy rum noull	ORIGINAL USE: reside co
TAX MAP 45 Black 10 P-17	ARCHITECT/ENGINEER:
COMMON NAME:	BUILDER/CONTRACTOR:
FUNCTIONAL TYPE: Farm house	
OWNER: TAHOMA FARMS	PHYSICAL CONDITION OF STRUCTURE:
ADDRESS:	Excellent () Good (X)
	Fair () Poor ()
ACCESSIBILITY TO PUBLIC:	THEME:
Yes () No () Restricted ()	STYLE:
EVEL OF SIGNIFICANCE:	DATE BUILT:
ocal () State () National ()	DATE BUILL:
ENERAL DESCRIPTION:	
Structural System	
1. Foundation: Stone (X) Brick () Concrete 2. Wall Structure A. Wood: Log (X) Post and Beam () Ballo	
B. Wood Bearing Masonry: Brick () Stone C. Iron () D. Steel () E. Other	() Concrete () Concrete Block ()
3. Wall Covering: Weatherboard () German Sid Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal () Le () Brick Veneer () Stone Veneer ()
4. Roof Structure	Other: Lyposed log
A. Truss: Wood (<) Iron () Steel () (B. Other:	Concrete ()
5. Roof Covering: Slate () Wood Shingle () Built Up () Rolled () Ti	Asphalt Shingle (*) Sheet Metal ()
6. Engineering Structure: 7. Other:	
Appendages: Porches () Towers () Cupolas () Ells () Wings () Other:	Dormers () Chimneys () Sheds ()
) Mansard () Gambrel () Jerkinhead () Bellcast () With Parapet ()
Number of Bays: 2 X	Entrance Location: side
Approximate Dimensions:	5100
	LOCAL ATTITUDES:
AREAT TO STRUCTURE:	Positive () Negative ()
No Threat () Zoning () Roads ()	Mixed () Other:

Number of Stories: 2 with full basement 2 X I Number of Bays:____ Approximate Dimensions: AREAT TO STRUCTURE: No Threat () Zoning () Roads () Development () Deterioration () Alteration () Other:

RELATED STRUCTURES: (Describe)	
STATEMENT OF SIGNIFICANCE:	
	C
REFERENCES:	4
1862 Martenet's Map: 3 mol shown 1877 LG & S Atlas:	
CURDOUNDING EMILIDONATION.	2-747.94
SURROUNDING ENVIRONMENT: Open Lane ()Woodland ()Scattered Buildings() Moderately Built Up ()Densely-Built Up () Residential () Commercial () ORGANIZATION:	
Agricultural () Industrial () Roadside Strip Development ()	
Other: DATE RECORDED:	10377





- 1. CARR-405 LOG HOUSE
- 2. Carroll County, Maryland
- 3. Joe Getty
- 4. November 1983
- 5. Md. Historical Trust, Annapolis, Md.
- 6. North facade (camera facing south)
- 7. 1/1